<u>Polymak</u>[®]

CHOP SAW

CM-CO355-3000

INSTRUCTION MANUAL

<u>Polymak</u>®

Polymak Tools (India) Pvt. Ltd

188/187,P.H Road,Alsa Towers,Kilpauk,Chennai.600 010 Tamilnadu,india

Tel.: 1800-309-4535
E-mail: info@polymak.co.in
Visit us at: www.polymak.co.in



Read and follow all safety precautions in instruction manual.

ENGLISH (Original Instructions)

SPECIFICATIONS


Model	CM-CO355-3000
Wheel diameter	355 mm
Hole diameter	25.4 mm
No load speed (min ⁻¹)	3,800
Dimensions (L x W x H)	57x34.8x42.5
Net weight	15 kg
Safety class	13 /II

- . Due to our continuing programme of research and development, the specifications herein are subject to change without notice
- Weight according to EPTA-Procedure 02/2005

Symbols

The following show the symbols used for the equipment. Be sure that you understand their meaning before use.

Read instruction manual.



X

Only for EU countries

Do not dispose of electric equipment together with household waste material! In observance of European Directive 2002/96/EC on waste electric and electronic equipment and its implementation in accordance with national law, electric equipment that have reached the end of their life must be collected separately and returned to an environmentally compatible recycling

Intended use

Intended use
The tool is intended for cutting in masonry and ferrous
materials with appropriate abrasive cut-off wheel. Follow
all laws and regulations regarding dust and work area health and safety in your country

Power supply

The tool should be connected only to a power supply of the same voltage as indicated on the nameplate, and can only be operated on single-phase AC supply. They are double-insulated and can, therefore, also be used from sockets without earth wire.

For public low-voltage distribution systems of between 220 V and 250 V.

Switching operations of electric apparatus cause voltage fluctuations. The operation of this device under unfavorable mains conditions can have adverse effects to the operation of other equipment. With a mains impedance equal or less than 0.22 Ohms it can be presumed that there will be no negative effects. The mains socket used for this device must be protected with a fuse or protective circuit breaker having slow tripping

SAFETY INSTRUCTIONS

WARNING! When using electric tools, basic safety precautions, including the following, should always be followed to reduce the risk of fire, electric shock and personal injury. Read all these instructions before operating this product and save these instructions. instructions.

For safe operations:

- Keep work area clean.
 Cluttered areas and benches invite injuries.
- Consider work area environment.
- Do not expose power tools to rain. Do not use
- power tools in damp or wet locations. Keep work area well lit. Do not use power tools where there is risk to cause fire or explosion. Guard against electric shock. Avoid body contact with earthed or grounded surfaces (e.g. pipes, radiators, ranges,
- refrigerators).
 Keep children away.

 **The initial content of the tool or extension cord.

 **The work area. Do not let visitors touch the tool or extension corr All visitors should be kept away from work area.
- Store idle tools.
- When not in use, tools should be stored in a dry, high or locked up place, out of reach of children.
- Do not force the tool. It will do the job better and safer at the rate for which it was intended.
- Use the right tool.

Do not force small tools or attachments to do the job of a heavy duty tool. Do not use tools for purposes not intended; for example, do not use circular saws to cut tree limbs or logs. Dress properly.

Do not wear loose clothing or jewellery, they can be caught in moving parts. Rubber gloves and non-skid footwear are recommended when working outdoors. Wear protecting hair covering to contain long hair.

Use safety glasses and hearing protection. Also use face or dust mask if the cutting operation is dusty.

Connect dust extraction equipment.

If devices are provided for the connection of dust extraction and collection facilities ensure these are 10 connected and properly used.

11. Do not abuse the cord.

Never carry the tool by the cord or yank it to disconnect it from the socket. Keep the cord away from heat, oil and sharp edges.

Secure work Use clamps or a vice to hold the work. It is safer than using your hand and it frees both hands to

operate the tool.

Do not overreach.
Keep proper footing and balance at all times.
Maintain tools with care.

Keep cutting tools sharp and clean for better and safer performance. Follow instructions for lubrication and changing accessories. Inspect tool cord periodically and if damaged have it repaired by an authorized service facility. Inspect extension cords periodically and replace, if damaged. Keep handles dry, clean and free from oil and grease. Disconnect tools.

When not in use, before servicing and when changing accessories such as blades, bits and

cutters.
Remove adjusting keys and wrenches. Form the habit of checking to see that keys and adjusting wrenches are removed from the tool before turning it on. Avoid unintentional starting. Do not carry a plugged-in tool with a finger on the switch. Ensure switch is off when plugging in.

Use outdoor extension leads. When tool is used outdoors, use only extension cords intended for outdoor use.

19 Stay alert. Watch what you are doing. Use common sense.

Do not operate tool when you are tired.

Check damaged parts.

Before further use of the tool, a guard or other part that is damaged should be carefully checked to determine that it will operate properly and perform its intended function. Check for alignment of

moving parts, free running of moving parts breakage of parts, mounting and any other

conditions that may affect its operation. A guard or other part that is damaged should be properly repaired or replaced by an authorized service center unless otherwise indicated in this instruction manual. Have defective switches replaced yan authorized service facility. Do not use the tool if the switch does not turn it on and off.

21.

Warning.
The use of any accessory or attachment, other than those recommended in this instruction manual or the catalog, may present a risk of

personal injury.

Have your tool repaired by a qualified person.

This electric tool is in accordance with the relevant safety requirements. Repairs should only be 22. carried out by qualified persons using origin pare parts, otherwise this may result onsiderable danger to the user.

ADDITIONAL SAFETY RULES FOR TOOL

- 1. Wear protective glasses. Also wear hearing protection during extended periods of peration
- Use only wheels recommended by the ose only wheels recommended by the manufacturer which have a maximum operating speed at least as high as "No Load RPM" marked on the tool's nameplate. Use only fiberglass-reinforced cut-off wheels. Check the wheel carefully for cracks or damage before operation. Replace cracked or
- damaged wheel immediately.
- Secure the wheel carefully.
 Use only flanges specified for this tool.
- See careful not to damage the spindle, flanges (especially the installing surface) or bolt, or the wheel itself might break.
 Keep guards in place and in working order, Hold the handle firmly. 6.

- Keep hands away from rotating parts. Make sure the wheel is not contacting the 10.
- work-piece before the switch is turned on.
 Before using the tool on an actual workpiece,
- let it simply run for several minutes first. Watch for flutter or excessive vibration that might be caused by poor installation or a poorly balanced wheel. Watch out for flying sparks when operating.
- They can cause injury or ignite combustible
- Remove material or debris from the area that might be ignited by sparks. Be sure that others are not in the path of the sparks. Keep a proper, charged fire extinguisher closely available.

- 14. Use the cutting edge of the wheel only. Never use side surface.
 15. If the wheel stops during the operation, makes
- an odd noise or begins to vibrate, switch off the tool immediately.


 Always switch off and wait for the wheel to
- come to a complete stop before removing,
- securing workpiece, working vise, changing work position, angle or the wheel itself.

 Do not touch the workpiece immediately after operation; it is extremely hot and could burn
- your skin. Store wheels in a dry location only.

SAVE THESE INSTRUCTIONS.

INSTALLATION

Securing cut-off



This tool should be bolted with two bolts to a level and stable surface using the bolt holes provided in the tool's base. This will help prevent tipping and possible personal

FUNCTIONAL DESCRIPTION

ACAUTION:

Always be sure that the tool is switched off and unplugged before adjusting or checking function on the tool.

Switch action



Switch trigger
 Lock button /
 Lock-off button

ACAUTION:

Before plugging in the tool, always check to see that the switch trigger actuates properly and returns to the "OFF" position when released.

For tool with lock button

To start the tool, simply pull the switch trigger. Release the switch trigger to stop.

For continuous operation, pull the switch trigger and then

push in the lock button.


To stop the tool from the locked position, pull the switch trigger fully, then release it.
For tool with lock-off button

To prevent the switch trigger from being accidentally pulled, a lock-off button is provided.

To start the tool, depress the lock-off button and pull the


switch trigger. Release the switch trigger to stop.

Stopper plate (except for European countries)




The stopper plate prevents the cut-off wheel from contacting the workbench or floor. When a new wheel is installed, set the stopper plate to position (A). When the wheel wears down to the extent that the lower portion of the workpiece is left uncut, set the stopper plate to position (B) to allow increased cutting capacity

Interval between vise and guide plate



Socket wrench
 Guide plate
 Move
 Hex bolts



The original spacing or interval between the vise and the guide plate is 0 - 170 mm. If your work requires wider spacing or Interval, proceed as follows to change the spacing or Interval.

Remove the two hex bolts which secure the guide plate.

Move the guide plate as shown in the figure and secure it using the hex bolts. The following interval settings are

possible: 35 - 205 mm

70 - 240 mm

∆CAUTION:

Remember that narrow workpieces may not be secured safely when using the two, wider interval settings.

Setting for desired cutting angle



Socket wrench
 Guide plate
 Hex bolts

To change the cutting angle, follow the procedure below:

- ange the cutting angle, follow the procedure below: Loosen the two hex bolts. Set the guide plate to the desired angle (0° 45°). For more accurate angle, use a protractor or triangle ruler. Keep the handle down so that the cut-off wheel extends into the base. At the same time, adjust the angle between the guide plate and the cut-off wheel with a protractor or triangle ruler. Tighten the hex bolts securely. At this time, make
- sure that the guide rule does not move.

 5. Check the angle again.

ACAUTION:

Never perform right miter cuts when the guide plate is set at the 35 - 205 mm or 70 - 240 mm position.

The scale on the guide plate is only a rough indication.

ASSEMBLY

Δ caution:

Always be sure that the tool is switched off and unplugged before carrying out any work on the tool.

Removing or installing cut-off wheel (Accessory)



Shaft lock
 Wheel guard
 Socket wrench
 Loosen
 Tighten

To remove the wheel, raise the wheel guard. Press the shaft lock so that the wheel cannot revolve and use the socket wrench to loosen the hex bolt by turning it counterclockwise. Then remove the hex bolt, outer flange and wheel. (Note: Do not remove the inner flange,

To install the wheel, follow the removal procedures in reverse.



1. O-ring
2. Inner flange
3. Ring
4. Spindle
5. Cut-off wheel
6. Outer flange
7. Hex bolt

ACAUTION:

- Be sure to tighten the hex bolt securely. Insufficient tightening of the hex bolt may result in severe injury. Use the socket wrench provided to help assure proper tightening.

 Always use only the proper inner and outer flanges which are provided with this tool.
- Always lower the wheel guard after replacing the

Securing workpiece




1. Vise plate 2. Vise nut 3. Vise handle

By turning the vise handle counterclockwise and then by turning the vise handle counterclockwise and then flipping the vise nut to the back, the vise is released from the shaft threads and can be moved rapidly in and out. To grip workpieces, push the vise handle until the vise plate contacts the workpiece. Fije the vise nut to the front and then turn the vise handle clockwise to securely retain the

∆CAUTION:

∴ Always set the vise nut to the front fully when securing the workpiece. Failure to do so may result in insufficient securing of the workpiece. This could cause the workpiece to be ejected or cause a dangerous breakage of the wheel.
When the cut-off wheel has worn down considerably, use a spacer block of sturdy, non-flammable material behind the workpiece as shown in the figure. You can more efficiently utilize the worn wheel by using the mid point on the periphery of the wheel to cut the workpiece. the periphery of the wheel to cut the workpiece.



When cutting workpieces over 85 mm wide at an angle attach a straight piece of wood (spacer) to the guide plate as shown in the figure. Attach this spacer with so through the holes in the guide plate.




Guide plate
 Straight piece of wood (Spacer)
 Over 85mm long


If you use a spacer block which is slightly narro the workpiece as shown in the figure, you can also utilize the wheel economically when worn down the wheel.

1. Diameter of

block 5. Vise



Long workpieces must be supported by blocks of non-flammable material on either side so that it will be level with the base top.



OPERATION

OPERATION.
Hold the handle firmly. Switch on the tool and wait until the wheel attains full speed before lowering gently into the cut. When the wheel contacts the workpiece, gradually bear down on the handle to perform the cut. When the cut is completed, switch off the tool and WAIT UNTIL THE WHEEL HAS COME TO A COMPLETE STOP before returning the handle to the fully elevated position.

∆CAUTION:

Proper handle pressure during cutting and maximum cutting efficiency can be determined by the amount of sparks that is produced while cutting. Your pressure on the handle should be adjusted to produce the maximum amount of sparks. Do not force the cut by applying excessive pressure on the handle. Reduced cutting efficiency, premature wheel wear, as well as, possible damage to the tool, cut-off wheel or workpiece may result

Cutting capacity

Max. cutting capacity varies depending upon the cutting angle and workpiece shape. Applicable wheel diameter:

Workpiec \emptyset **^** Cutting angle 90° 115 mm 119 mm 45° 115 mm 106 mm


Workpiece shape Cutting angle	A x B B	***
90°	102 mm × 194 mm 70 mm × 233 mm	137 mm
45°	115 mm × 103 mm	100 mm

Replacing carbon brushes



Remove and check the carbon brushes regularly. Replace when they wear down to the limit mark. Keep the carbon brushes clean and free to slip in the holders. Both carbon brushes should be replaced at the same time. Use only identical carbon brushes.

Use a screwdriver to remove the brush holder caps. Take out the worn carbon brushes, insert the new ones and secure the brush holder caps.



Brush holder cap
 Screwdriver

To maintain product SAFETY and RELIABILITY, repairs, to framitan product on a 11 similar instance. In any other maintenance or adjustment should be performed by EUROPA HILT Authorized Service Centers, always using EUROPA HILT replacement parts.

∆CAUTION:

- AUTION:
 Always be sure that the tool is switched off and unplugged before attempting to perform inspection or maintenance.

 Never use gasoline, benzine, thinner, alcohol or the like. Discoloration, deformation or cracks may

This serves to Inform you that all Europa HILT Product is thoroughly inspected and tested before leaving the factory. Subject to the following terms and conditions, the Product is warranty against defective materials and manufacturing defects for a period of Six (6) or twelve (12) months from the date of original purchase (applicable for purchases made from as evidenced from the sale or invoice/ Cash Sales (with products serial number).

Europa HILT Hot Air Guns, Batteries, Chargers, Power Tools, High Pressure Washer are entitled to 6 months

Europa HILT HEAVY DUTY Range Demolition Hammer, Rotary Hammer, Grinder under Brushless series Power Tools
Products are entitled to 1 Year Warranty Only.

3 times warranty repair are allowed for (Only Armature, Stator)
1 Year free labour charge

GENERAL TERMS AND CONDITIONS

6 Months Warranty only applicable for purchases made from the date of original purchase. To repair or replace, free of charge Conditions of warranty (Term and Conditions apply). For the same defect repair within warranty period.


• 3 times warranty repair are allowed for Power Tool (Only Armature, Stator & Switch)

- 6 Months Labor free (in state under warranty coverage)
 2 times for Measuring Tools and Garden Tools. This guarantee, however, does not cover damage caused by accident, misuse, unauthorized repairs, tampering, normal wear & tear, additions and modifications made to

WARRANTY LIMITATIONS AND EXCLUSIONS
Warranty will NOT cover or shall be null & void in any of the following events even during the warranty period:

- Damage resulting from normal wear and tear (Carbon brush/ holder/ cap, switch, gear, grinding/ cutting) wheels, bits, saw blades, etc..)
- Damage resulting from use of improper accessories, non-genuine replacement parts, disassembly, tampering, alteration and repairing in any way that affects its performance.
- Damage resulting from negligence, accident, disaster, improper storage or maintenance, abuse and misuse in evident caused by overloading the tool beyond its capacity.
- Abnormal voltage or the usage of generator, wrong usage not in accordance with the Operating Manual. If the serial number on the tool, seal on the battery and charger has been defaced or removed.
- If the receipt or invoice that display the date of purchase could not be present.
- •• In case of complaint, please send the tool, dismantled together with official proof of purchase. tax Invoice or receipt Stated with tool's serial no.to Europa HILT Authorized Service Centre or Main office.

PARTS DIAGRAM



CM-CO355-3000 Spare Parts List

	Part C	A. co. a		128 3 10	
Item	Description	QTY	Item	Description	QTY
1	Pan head screwST4x14	12	38	Clamp sheet	_1_
2	Motor housing cap	1	39	Hex nutM10X25	1
3	Pan head screwM5x45PT	4	40	Pressure Plate Shield	1
4	Motor housing	1	41	Hex nutM6x12PT	1
5	Stator	1	42	Screw M6X10	1
6	Pan head screwST5x70	2	43	Pan head screw M6x8	1
7	Left handle	1	44	movable guard	1
8	Cable 2*1 *2m	1	45	Hollow shaft	1
9	sheath	1	46	Hex nut/M6	1
10	tension disc	1	47	Spring washer/Φ6	1
11	Switch	1	48	Torsion spring	1
12	Right handle	1	49	Hex Nut\M10	1
13	Bearing 6000	1	50	Screw/M10x80	1
14	Washer	1	51	Shock rubber feet	4
15	Rotor	1	52	Base	1
16	Spring	2	53	Hex Nut\M10	3
17	Brush holder	2	54	Support bracke	1
18	Carbon brush	2	55	Flat washer	2
19	Pan head screwST3.5x8	2	56	Spring washer	3
20	Bearing 6202	2	57	Pan head screwST8x20	2
21	Baffle	1	58	Pinφ10x35	1
22	O-ring	1	59	Flat washer Ø	1
23	Spring	1	60	Flat washerφ8X15X1.5	2
24	Rubber column	1	61	Handle sleeve	1
25	Cutting arm	1	62	Screw rod handle	1
26	Gear	1	63	split pin	1
27	Cover	1	64	Vice nut	1
28	Bearing 6203	1	65	Washer\φ8.5×22×2	1
29	Spindle	1	66	Vice plate	1
30	Fixed guard	1	67	Pin	1
31	Hex Nut\M5	4	68	Pan head screwM6x10	1
32	Screw/M6x16T	4	69	Dust cover	1
33	Inner flange(90)	2	70	Fence	1
34	Spring	1	71	Flat washerφ10	2
35	Screw/M6x16	2	72	Spring washer@10	2
36	Spring	1	73	Screw10x20	2
37	Rubber Foot	1	74	wrench	1

Polymak®

Polymak Tools (India) Pvt. Ltd

188/187,P.H Road,Alsa Towers,Kilpauk,Chennai.600 010 Tamilnadu,india

Tel. : 1800-309-4535

E-mail : info@polymak.co.in Visit us at : www.polymak.co.in