


**Polymak®**

**PM6023-HD MAGNETIC DRILL**

Max Drilling Capacity: 23mm  
Magnetic Adhesion: 13000N  
No load speed: 330r/min  
Fixture: MT2  
Power: 1880W  
Weight: 21KG



[www.polymak.co.in](http://www.polymak.co.in)

**Polymak®**

**PM6023-HD SPARE PARTS LIST**

| No | Parts Name                 | Pcs | Seri No | INR | No | Parts Name             | Pcs | Seri No | INR |
|----|----------------------------|-----|---------|-----|----|------------------------|-----|---------|-----|
| 1  | MT-2 spindle               |     |         |     | 38 | Screw Nut 5            |     |         |     |
| 2  | Circrip                    |     |         |     | 39 | Board                  |     |         |     |
| 3  | 6205 RZ                    |     |         |     | 40 | Screw M3               |     |         |     |
| 4  | Screw M6                   |     |         |     | 41 | Connector              |     |         |     |
| 5  | Gear Box                   |     |         |     | 42 | Connector              |     |         |     |
| 6  | Internal screw sleeve      |     |         |     | 43 | Rack part              |     |         |     |
| 7  | Flat Gear                  |     |         |     | 44 | Screw M8               |     |         |     |
| 8  | Middle Cover               |     |         |     | 45 | Spring Pad             |     |         |     |
| 9  | RZ                         |     |         |     | 46 | Flat Pad               |     |         |     |
| 10 | Cluster Gear               |     |         |     | 47 | Magnetic Base          |     |         |     |
| 11 | Bearing 608                |     |         |     | 48 | Circrip                |     |         |     |
| 12 | Bearing 6201               |     |         |     | 49 | Lift Gear              |     |         |     |
| 13 | Armature                   |     |         |     | 50 | Lift Spindle           |     |         |     |
| 14 | Bearing 6000               |     |         |     | 51 | Lifter Bar             |     |         |     |
| 15 | Air Deflector              |     |         |     | 52 | Bakelite Ball          |     |         |     |
| 16 | Bearing 6201               |     |         |     | 53 | Indicator Light        |     |         |     |
| 17 | Screw M5                   |     |         |     | 54 | Fuse                   |     |         |     |
| 18 | Spring Pad                 |     |         |     | 55 | Magnetic Switch        |     |         |     |
| 19 | Flat Pad                   |     |         |     | 56 | Power Switch           |     |         |     |
| 20 | Stator                     |     |         |     | 57 | Circuit Panel Assembly |     |         |     |
| 21 | Field Coil Cover           |     |         |     | 58 | Holder Washer          |     |         |     |
| 22 | Field Coil Housing         |     |         |     | 59 | Cord Sleeve            |     |         |     |
| 23 | Brush Holder               |     |         |     | 60 | Cord                   |     |         |     |
| 24 | Carbon Brush               |     |         |     |    |                        |     |         |     |
| 25 | Brush Holder               |     |         |     |    |                        |     |         |     |
| 26 | Motor Back Cover           |     |         |     |    |                        |     |         |     |
| 27 | Screw M6                   |     |         |     |    |                        |     |         |     |
| 28 | Connector                  |     |         |     |    |                        |     |         |     |
| 29 | Screw M6                   |     |         |     |    |                        |     |         |     |
| 30 | Lifting Guide Plate        |     |         |     |    |                        |     |         |     |
| 31 | Screw M5                   |     |         |     |    |                        |     |         |     |
| 32 | Screw M6                   |     |         |     |    |                        |     |         |     |
| 33 | Rack                       |     |         |     |    |                        |     |         |     |
| 34 | Screw M5                   |     |         |     |    |                        |     |         |     |
| 35 | Iron Bar                   |     |         |     |    |                        |     |         |     |
| 36 | Back Cover of Lift Spindle |     |         |     |    |                        |     |         |     |
| 37 | Screw M5                   |     |         |     |    |                        |     |         |     |