




4100 MARBLE CUTTER 110mm



Polymak
All Dimensions Given In Millimeters

4100 - 4" Marble Cutter

Item No	Part No	Description
1	113002	Base
2	238001	Wing Bolt
3	319025	sleeve
4	231005	screw M4x15
5	273006	Spring key
6	162001A	gear case
7	211003	bearing
8	252004	retaining ring
9	136035	gear
10	251005	retaining ring
11	243005	wave washer
12	143014	sleeve
13	211067	bearing
14	276002	key
15	133031	spindle
16	336002	seal
17	342002	Paper washer
18	161002A	bearing box
19	182016	inner flange
20	242004	washer
21	241002	spring washer
22	234008	screw M5x25
23	182010	outer flange
24	234003	Bolt M6x18 left hand
25	333002	O ring
26	252001	retainer
27	136036	pinion
28	211023	bearing
29	276001	key
30	442041	armature
31	319024	spacer
32	211021	bearing
33	114001	washer
34	333015	O ring
35	221031	screw ST5x65
36	441040	Fieldcoil
37	321005	baffle plate
38	314026A	handle cover
39	335002	small switch cap
40	335003	big switch cap
41	445013	switch
42	338016	rubber
43	313002A	field housing
44	541006	name plate
45	222002	screw ST4x16
46	231010	screw M5x25
47	235001	screw M5x8
48	432001A	brush holder

Item No	Part No	Description
49	431007B	Carbon brush
50	433002A	brush cap
51	411029	cable
52	332006	cord protector
53	318001	cord clamp
54	443007	capacitor
55	437001	terminal board
56	623021	spanner
57	623033	socket wrench
58	624005	water accessory
59	624008	hose
60	624001	pipe